



CDI Editor インストールガイド

動作環境

OS Windows XP SP2 32ビット正規版
Windows Vista SP1 32ビット正規版
HDD 250MB以上の空き容量

* .net framework 3.0 が必要とする XP SP2 以降の Windows が必須条件となります。
Windows 2000 などではインストールすることができません。


● 自作機等も含め、多種多様なハードウェア構成を全て網羅して ありませんので、サポート等は致しかねます。

● 本ソフトウェアをインストールしたことによりコンピュータシステム等に損害が生じたとしても、また、それが間接的であったとしても、弊社は責任を負いません。
また、いかなる損害賠償も一切行いません。

● 推奨環境以外でも動作する可能性はありますが、動作保証は一切ありません。


インストール

1 ファイルを開き、setup.exeを実行します。




- 2 .net Framework 3.5 Crystal Reportのインストールを行います。
(ソフトを動作させる為に必要な、マイクロソフト社の製品です)

下図のようなメッセージが表示されますので、Acceptをクリックします。
(.net Framework 3.5用)




- 3 同じく、下図のようなメッセージが表示されますので、Acceptをクリックします。
(Crystal Report用)



上記ソフトのインストールには、数分かかる可能性があります。

- 4 インストール終了時に再起動が必要な場合があります。
Yesで再起動を行います。




5 パワーレブRW-CDIのソフトウェア (CDI Editor)をインストールします。


同意された場合のみAgreeにチェックをし次に進みます。
それ以外の場合は、キャンセルをクリックします。




6 次に進みます。




- 7 インストール先のフォルダーを選択します。
(デフォルト推奨)




- 8 次に進みます。




- 9 デバイスドライバーのインストール
インストール先のフォルダーを選択します。
(デフォルト推奨)



- 10 警告メッセージが表示されますが問題ありませんので続行を押してください




- 11 終了のメッセージが表示されればインストール完了です。




ドライバー設定


- 1 CDIユニット初回接続時に「新しいハードウェアの検出ウィザード」が表示されます。「いいえ、今回は接続しません」にチェックし次へ進みます。



- 2 「一覧または特定の場所からインストールする」にチェックし次へ進みます。




- 3 「次の場所で最適のドライバを検索する」をチェックし、「次の場所を含める」にて参照ボタンを押します。




- 4 「フォルダの参照」でプログラムファイルの「KITACO」-「MCU」-「CP210X」を指定します。
(デフォルトでインストールしていない場合は、ドライバの保存先を参照します)




- 5 選択できたら、次へ進みます。



6 警告メッセージが表示されますが問題ありませんので続行を押してください



7 以上で、インストールは完了です。





CDI Editor INSTALL GUIDE

Operating Environment

OS Windows XP SP2 32bit
Windows Vista SP1 32bit
HDD 250MB or above FREE SPACE


Requires Windows XP SP2 or above that .net framework 3.0 requires to work with.
It does not work with Windows 2000.

Kitaco shall not be liable for compensation or damages of any kind whatsoever,
incurred by reason
of logging with your PC, because there are too wide variety of computers including
hand-made PC.

No guarantee of proper operation, though it might activate without recommended
OS and browser environments.

INSTALL


1. Open files and execute "setup.exe".




2. Install net. Framework 3.5, Crystal Report.

(It is a program provided by Microsoft Corporation for setting up this software)

If message like below is shown, click "Accept".
(.net Framework 3.5)




3. If message like below is shown, click "Accept". (Crystal Report)



To install above software, it might take a few minutes.

4. It might be required to reboot your PC. Click "Yes" to reboot.




5. Install POWER REV RW-CDI software (CDI Editor)


If you agree, check "Agree" and go next. If you do not, click "Cancel (Q)".




6. Click "Next (N)".




7. Select destination to install. (Default folder is recommended.)




8. Click "Next (N)".




9. Install device driver. Select destination to install. (Default folder is recommended.)



10. Warning message might be shown, but press "Continue '(C)'", to continue.




11. If "Installation Complete" message is shown, installation is completed.




DRIVER SETTING


1. When first connected to CDI unit, "New Hardware Detection Wizard" is shown. Check "No, I will not connect this time (N)" and go next (N).



2. Check "Install from the list or specific location (S)" and go next (N).




3. Check "Search the best driver in the next location (S)"
 , Include next location (O) and press Browse (R)".




4. Select "KITACO", "MCU" and "CP210X".
 (If it is not installed by default, refer to destination of driver.)



5. After chosen, go next (N).



6. Warning message might be shown, but press "Continue (C)", to continue.



7. If "Installation Complete" message is shown, installation is completed.

